

TEST REPORT - LEGIONELLA

Customer Name : Tank Care Tanks Cleaning
Address : Al Ain , UAE
Contact person : Mr. Mahmoud M.Abd El Radi



Report no.: AR25-015588-2

Project : Quality Assurance
Project No. :-
Contract/LPO No. : Cash
Project location :-
Test location : AHSL - Abu Dhabi

Job No. : AJ25-005500
Sample No. : AS25-015588
Report Date : 01/03/2025
Test Date : 19/02/2025-01/03/2025

Sample description : POTABLE WATER
Sampling method : APHA 9060 A, BS EN 7592:2022
Sampling location : Al Ain Junior School
Sampling Date&Time : 18/02/2025 9:30 AM
Collection Temp.(°C) : 24.0
Receipt Temp. (°C) : 14.5 (L)
Sample delivered by : AHSL representative

Sampled by : AHSL representative
Source of sample : Tank Care Tanks Cleaning - Al Ain
Sampling Cert. No : 244165/1
On-site treatment : Transported in cool box
Receipt Temp.(°C) : 3.3 (M)
Received Date&Time : 18/02/2025 07:40 PM

TEST RESULTS

Test Parameter	Test Method	Unit	MoU	MDL	Result	Limits	Remarks
Legionella sp.	^K ISO 11731: 2017 (Matrix A/ Procedure 7/ Medium C)	CFU/L	N/A	1	<1	<1	Satisfactory
Legionella pneumophila serogroup 1	^A ISO 11731: 2017	CFU/L	N/A	1	Not Detected	-	-
Legionella pneumophila serogroup 2-15	^A ISO 11731: 2017	CFU/L	N/A	1	Not Detected	-	-

Tested by : EM00759

Verified by : EM00471

Test Method Variations : None

Remarks : None

Specifications

The water Quality Regulations 2025, Department of Energy, Abu Dhabi

^A Indicates AHSL Abu Dhabi is accredited by ENAS (NAL 013)

^K Indicates AHSL Abu Dhabi is accredited by ENAS (NAL 013) and EIAC (LB-TEST-023)

MDL- Method Detection Limit MoU - Measurement of uncertainty



Suhail

Approved by : Mr. Suhail K.P, HOD - Microbiological Dept.

THIS IS A COMPUTER GENERATED REPORT AND NO SIGNATURE REQUIRED

This report relates only to the sample tested and shall only be reproduced in full and with the written approval of AHS laboratories

TEST REPORT – MICROBIOLOGY

Customer Name : Tank Care Tanks Cleaning
Address : Al Ain , UAE
Contact person : Mr. Mahmoud M.Abd El Radi



Report no.: AR25-015588-1

Project : Quality Assurance

Project No. :-

Job No. : AJ25-005500

Contract/LPO No. : Cash

Sample No. : AS25-015588

Project location :-

Report Date : 20/02/2025

Test location : AHSL - Abu Dhabi

Test Date : 18/02/2025-20/02/2025

Sample description : POTABLE WATER

Sampled by : AHSL representative

Sampling method : APHA 9060 A, BS EN 7592:2022

Source of sample : Tank Care Tanks Cleaning - Al Ain

Sampling location : Al Ain Junior School

Sampling Cert. No : 244165/1

Sampling Date&Time : 18/02/2025 9:30 AM

On-site treatment : Transported in cool box

Collection Temp.(°C) : 24.0

Receipt Temp.(°C) : 3.3 (M)

Receipt Temp. (°C) : 14.5 (L)

Received Date&Time : 18/02/2025 07:40 PM

Sample delivered by : AHSL representative

TEST RESULTS

Test Parameter	Test Method	Unit	MoU	MDL	Result	Limits	Remarks
Aerobic Colony Count (Total Bacterial Count)	^K ISO 6222	CFU/mL	N/A	1	0	-	Satisfactory
Total Coliforms	^K APHA 9222 B; 24th Ed 2023	CFU/100mL	N/A	1	0	0 max.	Satisfactory
Fecal Coliforms	^K APHA 9221 E.1; 24th Ed 2023	CFU/100mL	N/A	1	0	0 max.	Satisfactory
<i>Escherichia coli</i>	^K APHA 9222 B; 24th Ed 2023	CFU/100mL	N/A	1	0	0 max.	Satisfactory
<i>Pseudomonas aeruginosa</i>	^K BS EN 16266: 2008	CFU/100mL	N/A	1	0	0 max.	Satisfactory
<i>Fecal streptococci/Enterococci</i>	^K APHA 9230 C; 24th Ed 2023	CFU/100mL	N/A	1	0	0 max.	Satisfactory

Tested by : EM00530, EM00655

Verified by : EM00530

Test Method Variations : None

Remarks : None

Specifications

The water Quality Regulations 2025, Department of Energy, Abu Dhabi

^KIndicates AHSL Abu Dhabi is accredited by ENAS (NAL 013) and EIAC (LB-TEST-023)

MDL- Method Detection Limit MoU - Measurement of uncertainty



Suhail

Approved by : Mr. Suhail K.P, HOD - Microbiological Dept.

THIS IS A COMPUTER GENERATED REPORT AND NO SIGNATURE REQUIRED

This report relates only to the sample tested and shall only be reproduced in full and with the written approval of AHS laboratories

TR/CM G3/Rev00

Page 1 of 1

Report no.: AR25-015588-1

ABU DHABI, U.A.E.,
P.O. BOX 31039
TEL.: (02) 5542234
FAX : (02) 5547015

DUBAI, U.A.E.
P.O. BOX 16756
TEL.: (04) 3472201
FAX : (04) 3472727

JEBEL ALI, U.A.E.
P.O. BOX 16756
TEL.: (04) 8818461
FAX : (04) 8818461

RAS AL KHAIMAH, U.A.E.
P.O. BOX 34987
TEL.: (07) 2432328
FAX : (07) 2432393

KALBA, SHARJAH, U.A.E.
P.O. BOX 145133
TEL.: (09) 2779543
FAX : (09) 2779545

E-mail : alhoty@alhotystanger.ae, Website : www.alhotystangeruae.com



Land of guidance

Water.Desalination Equipment Trading.LLC

AL HUDA DACES TRADING WATER TREATMENT

037619091

050-7219926



٧٦١٩٠٩١-٠٣

٧٢١٩٩٢٦-٠٥

Make an agreement

On Monday, 12/16/2024 AD, an agreement was reached between: the first party

Ard Al Huda for Water Desalination Equipment Trading LLC /

The second party / Al Ain Preparatory School. It was agreed between the two parties that the first party would carry out maintenance work on 12 drinking water refrigerators for a period of one year.

-1- Installing 12 refrigerator protectors 12,000 dirhams

2 - Installation of 12 triple filters 500 dirhams

3 - Permit for 12 refrigerators, 700 dirhams, with a white filter replacement every month.

Replace the first and second carbon every four months, and wash and sterilize the refrigerator every four months.

4 - Project duration is 1 year from the start date of the contract.

5 - The value of the first year is 26,400 thousand dirhams, to be paid in 2 installments.



Al Ain Preparatory School

First party

Ard Al Huda for Water Desalination Equipment Trading LLC



مركز المياه في كل

P.O. Box: 88072, Abu Dhabi - Al Ain - UAE.

P.O.Box: 88072, Abu Dhabi - Al Ain - United Kingdom.



ارض الهدى
لتجارة اجهزة تحلية المياه ذ.م.م.
AL HUDA LAND
WATER TREATMENT DEVICES TRADING L.L.C.

037619091

050-7219926



٧٦١٩٠٩١-٠٢

٧٢١٩٩٢٦-٠٥٠

عقد إتفاق

انه في يوم الاثنين الموافق 2024/12/16 م تم الاتفاق بين كل من : الطرف الأول / ارض الهدى لتجاره اجهزه تحلية المياه ذ م م

الطرف الثاني / مدرسة العين التمهيدية تم الاتفاق بين الطرفين على ان يقوم الطرف الأول باعمال صيانته عدد 12 ثلاجات مياه شرب لمدة سنة

1- تركيب عدد 12 حمايه ثلاجه 12000 الف درهم

2 - تركيب عدد 12 فلتر ثلاثي 500 درهم

3 - تصريح عدد 12 ثلاجة 700 درهم مع تبديل الفلتر ابيض كل واحد شهر
تبديل الكربون الأول والثاني كل أربعة شهور على ان يتم غسيل و تعقيمة ثلاجة
أربعة شهور

4 - مدة المشروع ١ سنة من تاريخ بداية العقد

5 - قيمة السنة الأول 26,400 الف درهم على انا تعطه على 2 دفعات



الطرف الأول

ارض الهدى لتجاره اجهزه تحلية المياه ذ م م



عزت الوكيل صاحب

ص.ب. : ٨٨٠٧٢ , ابو ظبي - العين - ا.ع.م.

P.O.Box: 88072, Abudhabi - Al Ain - U.A.E.

TANK CARE
TANKS CLEAN



تانك كير
لتنظيف الخزانات

Date: 19/02/ 2025

Number: 1643/ 2025

Certificate

We certified that we did cleaning and disinfection Of **Al Ain Juniors**

School Water Tank and removed all dirt and sand and organic mineral soil and fungi The condition Of Water Tank is very good.

We used Special chemical approved from all Concerns Disinfection for Four months.

Best Regards



Project information chart

Customer : Al Ain Juniors School				Contact person:			
Site address: Al Ain				Work order no.			
Tel:		Mobile:		Fax:			
Current cleaning date 16/02/2025				Last cleaned: UNKNOWN			
Next cleaning date 15/08/2025				Hours worked		Team	
Type of building	<input type="checkbox"/>	commercial	<input type="checkbox"/>	residential	<input type="checkbox"/>	Other	
Location of water storage tank	/	Roof	<input type="checkbox"/>	Ground	<input type="checkbox"/>	Basement	<input type="checkbox"/>
Tank No 6	600 Gallon						
<input type="checkbox"/>	Concrete uncontested	<input type="checkbox"/>	Molded fiber glass	<input type="checkbox"/>	GRP Panel	<input type="checkbox"/>	Steel panel
<input type="checkbox"/>	Concrete coated	<input type="checkbox"/>	Galvanized	/	Polyurethane	<input type="checkbox"/>	Others
Quantity of water	<input type="checkbox"/>	Full	<input type="checkbox"/>	Half full	/	Empty	
Condition of tank	<input type="checkbox"/>	Clean	<input type="checkbox"/>	Dirty	/	Very dirty	
CONTAMINATION							
Bio – film/staining	/	Yes	<input type="checkbox"/>	No	sediment	<input type="checkbox"/>	Yes
Mold	/	Yes	<input type="checkbox"/>	No	Algae	/	Yes
PHYSICAL ATTRIBUTES							
Lid/covers fitted	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Damaged		
Leaks	<input type="checkbox"/>	Yes	/	No	Where:	Valves	Tank
Pumps working	/	Yes	<input type="checkbox"/>	No	Valves working	/	Yes
Cover	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No		<input type="checkbox"/>	No
ACCESS:							
Ladder inside	<input type="checkbox"/>	Yes	/	No	Ladder outside	<input type="checkbox"/>	Yes
Pipes disinfected	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No		<input type="checkbox"/>	No
Power	<input type="checkbox"/>	7.4			Lap test	<input type="checkbox"/>	No
Recommended frequency of cleaning	<input type="checkbox"/>	Yearly	/	Every 6 month	<input type="checkbox"/>	Other	

Project information chart

Customer : Al Ain Juniors School				Contact person:			
Site address: Al Ain				Work order no.			
Tel:		Mobile:		Fax:			
Current cleaning date 16/ 02/2025				Last cleaned: UNKNOWN			
Next cleaning date 15/08/2025				Hours worked		Team	
Type of building		<input type="checkbox"/> commercial	<input type="checkbox"/> residential	<input type="checkbox"/> Other			
Location of water storage tank		<input checked="" type="checkbox"/> Roof	<input type="checkbox"/> Ground	<input type="checkbox"/> Basement	<input type="checkbox"/> underground		
Tank No 5		600 Gallon					
<input type="checkbox"/> Concrete uncontested	<input type="checkbox"/> Molded fiber glass	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> Steel panel				
<input type="checkbox"/> Concrete coated	<input type="checkbox"/> Galvanized	<input checked="" type="checkbox"/> Polyurethane	<input type="checkbox"/> Others				
Quantity of water		<input type="checkbox"/> Full	<input type="checkbox"/> Half full	<input checked="" type="checkbox"/> Empty			
Condition of tank		<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very dirty			
CONTAMINATION							
Bio – film/staining		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	sediment		<input type="checkbox"/> Yes	<input type="checkbox"/> No
Mold		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Algae		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
PHYSICAL ATTRIBUTES							
Lid/covers fitted		<input type="checkbox"/> Yes	<input type="checkbox"/> No	Damaged			
Leaks	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Where:		Valves	Tank	Pipes
Pumps working	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Valves working		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Cover	<input type="checkbox"/> Yes	<input type="checkbox"/> No					
ACCESS:							
Ladder inside	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Ladder outside		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Pipes disinfected	<input type="checkbox"/> Yes	<input type="checkbox"/> No			<input type="checkbox"/> No		
Powel	<input type="checkbox"/> 7.4			Lap test		<input type="checkbox"/> No	
Recommended frequency of cleaning			<input type="checkbox"/> Yearly	<input checked="" type="checkbox"/> Every 6 month	<input type="checkbox"/> Other		

Project information chart

Customer : Al Ain Juniors School				Contact person:			
Site address: Al Ain				Work order no.			
Tel:		Mobile:		Fax:			
Current cleaning date 16/ 02/2025				Last cleaned: UNKNOWN			
Next cleaning date 15/08/2025				Hours worked		Team	
Type of building	<input type="checkbox"/>	commercial	<input type="checkbox"/>	residential	<input type="checkbox"/>	Other	
Location of water storage tank	/	Roof	<input type="checkbox"/>	Ground	<input type="checkbox"/>	Basement	<input type="checkbox"/>
Tank No 4	600 Gallon						
<input type="checkbox"/>	Concrete uncontested	<input type="checkbox"/>	Molded fiber glass	<input type="checkbox"/>	GRP Panel	<input type="checkbox"/>	Steel panel
<input type="checkbox"/>	Concrete coated	<input type="checkbox"/>	Galvanized	/	Polyurethane	<input type="checkbox"/>	Others
Quantity of water	<input type="checkbox"/>	Full	<input type="checkbox"/>	Half full	/	Empty	
Condition of tank	<input type="checkbox"/>	Clean	<input type="checkbox"/>	Dirty	/	Very dirty	
CONTAMINATION							
Bio – film/staining	/	Yes	<input type="checkbox"/>	No	sediment	<input type="checkbox"/>	Yes
Mold	/	Yes	<input type="checkbox"/>	No	Algae	/	Yes
PHYSICAL ATTRIBUTES							
Lid/covers fitted	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Damaged		
Leaks	<input type="checkbox"/>	Yes	/	No	Where:	Valves	Tank
Pumps working	/	Yes	<input type="checkbox"/>	No	Valves working	/	Yes
Cover	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No		<input type="checkbox"/>	No
ACCESS:							
Ladder inside	<input type="checkbox"/>	Yes	/	No	Ladder outside	<input type="checkbox"/>	Yes
Pipes disinfected	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No		<input type="checkbox"/>	No
Powel	<input type="checkbox"/>	7.4			Lap test	<input type="checkbox"/>	No
Recommended frequency of cleaning	<input type="checkbox"/>	Yearly	/	Every 6 month	<input type="checkbox"/>	Other	

Project information chart

Customer : Al Ain Juniors School				Contact person:			
Site address: Al Ain				Work order no.			
Tel:		Mobile:		Fax:			
Current cleaning date 16/02/2025				Last cleaned: UNKNOWN			
Next cleaning date 15/08/2025				Hours worked		Team	
Type of building		<input type="checkbox"/>	commercial	<input type="checkbox"/>	residential	<input type="checkbox"/>	Other
Location of water storage tank		/	Roof	<input type="checkbox"/>	Ground	<input type="checkbox"/>	Basement
Tank No 3		600 Gallon					
<input type="checkbox"/>	Concrete uncontested	<input type="checkbox"/>	Molded fiber glass	<input type="checkbox"/>	GRP Panel	<input type="checkbox"/>	Steel panel
<input type="checkbox"/>	Concrete coated	<input type="checkbox"/>	Galvanized	/	Polyurethane	<input type="checkbox"/>	Others
Quantity of water		<input type="checkbox"/>	Full	<input type="checkbox"/>	Half full	/	Empty
Condition of tank		<input type="checkbox"/>	Clean	<input type="checkbox"/>	Dirty	/	Very dirty
CONTAMINATION							
Bio – film/staining		/	Yes	<input type="checkbox"/>	No	sediment	<input type="checkbox"/>
Mold		/	Yes	<input type="checkbox"/>	No	Algae	/
PHYSICAL ATTRIBUTES							
Lid/covers fitted		<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Damaged	<input type="checkbox"/>
Leaks	<input type="checkbox"/>	Yes	/	No	Where:	Valves	Tank
Pumps working	/	Yes	<input type="checkbox"/>	No	Valves working	/	Yes
Cover	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No		<input type="checkbox"/>	No
ACCESS:							
Ladder inside	<input type="checkbox"/>	Yes	/	No	Ladder outside	<input type="checkbox"/>	Yes
Pipes disinfected	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No		<input type="checkbox"/>	No
Powel	<input type="checkbox"/>	7.4			Lap test	<input type="checkbox"/>	No
Recommended frequency of cleaning				<input type="checkbox"/>	Yearly	/	Every 6 month
				<input type="checkbox"/>	Other		

Project information chart

Customer : Al Ain Juniors School				Contact person:			
Site address: Al Ain				Work order no.			
Tel:		Mobile:		Fax:			
Current cleaning date 16/02/2025				Last cleaned: UNKNOWN			
Next cleaning date 15/08/2025				Hours worked		Team	
Type of building		<input type="checkbox"/> commercial	<input type="checkbox"/> residential	<input type="checkbox"/> Other			
Location of water storage tank		<input checked="" type="checkbox"/> Roof	<input type="checkbox"/> Ground	<input type="checkbox"/> Basement	<input type="checkbox"/> underground		
Tank No 3		600 Gallon					
<input type="checkbox"/> Concrete uncontested	<input type="checkbox"/> Molded fiber glass	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> Steel panel				
<input type="checkbox"/> Concrete coated	<input type="checkbox"/> Galvanized	<input checked="" type="checkbox"/> Polyurethane	<input type="checkbox"/> Others				
Quantity of water		<input type="checkbox"/> Full	<input type="checkbox"/> Half full	<input checked="" type="checkbox"/> Empty			
Condition of tank		<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very dirty			
CONTAMINATION							
Bio – film/staining		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	sediment		<input type="checkbox"/> Yes	<input type="checkbox"/> No
Mold		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Algae		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
PHYSICAL ATTRIBUTES							
Lid/covers fitted		<input type="checkbox"/> Yes	<input type="checkbox"/> No	Damaged			
Leaks	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Where:		Valves	Tank	Pipes
Pumps working	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Valves working		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Cover	<input type="checkbox"/> Yes	<input type="checkbox"/> No					
ACCESS:							
Ladder inside	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Ladder outside		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Pipes disinfected	<input type="checkbox"/> Yes	<input type="checkbox"/> No			<input type="checkbox"/> No		
Powel	<input type="checkbox"/> 7.4			Lap test		<input type="checkbox"/> No	
Recommended frequency of cleaning			<input type="checkbox"/> Yearly	<input checked="" type="checkbox"/> Every 6 month	<input type="checkbox"/> Other		

Project information chart

Customer : Al Ain Juniors School				Contact person:			
Site address: Al Ain				Work order no.			
Tel:		Mobile:		Fax:			
Current cleaning date 16/ 02/2025				Last cleaned: UNKNOWN			
Next cleaning date 15/08/2025				Hours worked		Team	
Type of building	<input type="checkbox"/>	commercial	<input type="checkbox"/>	residential	<input type="checkbox"/>	Other	
Location of water storage tank	/	Roof	<input type="checkbox"/>	Ground	<input type="checkbox"/>	Basement	<input type="checkbox"/>
Tank No 2	600 Gallon						
<input type="checkbox"/>	Concrete uncontested	<input type="checkbox"/>	Molded fiber glass	<input type="checkbox"/>	GRP Panel	<input type="checkbox"/>	Steel panel
<input type="checkbox"/>	Concrete coated	<input type="checkbox"/>	Galvanized	/	Polyurethane	<input type="checkbox"/>	Others
Quantity of water	<input type="checkbox"/>	Full	<input type="checkbox"/>	Half full	/	Empty	
Condition of tank	<input type="checkbox"/>	Clean	<input type="checkbox"/>	Dirty	/	Very dirty	
CONTAMINATION							
Bio – film/staining	/	Yes	<input type="checkbox"/>	No	sediment	<input type="checkbox"/>	Yes
Mold	/	Yes	<input type="checkbox"/>	No	Algae	/	Yes
PHYSICAL ATTRIBUTES							
Lid/covers fitted	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Damaged		
Leaks	<input type="checkbox"/>	Yes	/	No	Where:	Valves	Tank
Pumps working	/	Yes	<input type="checkbox"/>	No	Valves working	/	Yes
Cover	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No			No
ACCESS:							
Ladder inside	<input type="checkbox"/>	Yes	/	No	Ladder outside	<input type="checkbox"/>	Yes
Pipes disinfected	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	<input type="checkbox"/>	No	
Powel	<input type="checkbox"/>	7.4			Lap test	<input type="checkbox"/>	No
Recommended frequency of cleaning	<input type="checkbox"/>	Yearly	/	Every 6 month	<input type="checkbox"/>	Other	

Project information chart

Customer : Al Ain Juniors School				Contact person:			
Site address: Al Ain				Work order no.			
Tel:		Mobile:		Fax:			
Current cleaning date 16/ 02/2025				Last cleaned: UNKNOWN			
Next cleaning date 15/08/2025				Hours worked		Team	
Type of building		<input type="checkbox"/> commercial	<input type="checkbox"/> residential	<input type="checkbox"/> Other			
Location of water storage tank		<input checked="" type="checkbox"/> Roof	<input type="checkbox"/> Ground	<input type="checkbox"/> Basement	<input type="checkbox"/> underground		
Tank No 1		600 Gallon					
<input type="checkbox"/> Concrete uncontested	<input type="checkbox"/> Molded fiber glass	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> Steel panel				
<input type="checkbox"/> Concrete coated	<input type="checkbox"/> Galvanized	<input checked="" type="checkbox"/> Polyurethane	<input type="checkbox"/> Others				
Quantity of water		<input type="checkbox"/> Full	<input type="checkbox"/> Half full	<input checked="" type="checkbox"/> Empty			
Condition of tank		<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very dirty			
CONTAMINATION							
Bio – film/staining		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	sediment		<input type="checkbox"/> Yes	<input type="checkbox"/> No
Mold		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Algae		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
PHYSICAL ATTRIBUTES							
Lid/covers fitted		<input type="checkbox"/> Yes	<input type="checkbox"/> No	Damaged			
Leaks	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Where:		Valves	Tank	Pipes
Pumps working	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Valves working		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Cover	<input type="checkbox"/> Yes	<input type="checkbox"/> No					
ACCESS:							
Ladder inside	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Ladder outside		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Pipes disinfected	<input type="checkbox"/> Yes	<input type="checkbox"/> No			<input type="checkbox"/> No		
Powel	<input type="checkbox"/> 7.4			Lap test		<input type="checkbox"/> No	
Recommended frequency of cleaning			<input type="checkbox"/> Yearly	<input checked="" type="checkbox"/> Every 6 month	<input type="checkbox"/> Other		